


Inspection Report (<input checked="" type="checkbox"/> 1ST <input type="checkbox"/> 2ND)		PENDING
<input checked="" type="checkbox"/> Pre-shipment <input type="checkbox"/> ON-LINE <input type="checkbox"/> IN PROCESS <input type="checkbox"/> FULL		
Summary Section		Service Number: F-QC 2506101834212043
	ProductName	Maternitypillow
	Itemnumber	Blue,Pink
	P/Onumber	---
	Quantity	1100pieces
	Clientname	---
	Suppliername	---
	Inspectiondate	2025-06-11
	Inspectionlocation	QingdaoShandongChina

INSPECTOR

	
Inspector: Collin	Inspector in factory / Inspector en la fabrica
Arrival time at the factory / Llegada a fabrica	Departure time from the factory / Salida de fabrica
9:30AM	11:20PM

Category	Con form		Comment
1. Quantity	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	Special attention 1
2. Product description / style / color	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	Special attention 2
3. Workmanship	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	
4. Testing/ checking	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	
5. Data measurement	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	
6. Packaging	<input type="checkbox"/> YES	<input checked="" type="checkbox"/> NO	Special attention 3

7. Marking	<input checked="" type="checkbox"/> YES	<input type="checkbox"/> NO	
------------	---	-----------------------------	--

OVERALL SUGGESTION	Pending
	Pending client review and approval

Special Attention				
1> When we arrived at the factory, all the products have finished but not finish packing, blue packed 430pcs, Pink packed 300pcs. 2> There is no sample for inspection reference. 3> The stickers on the outer box of the bulk goods have not been attached.				
Defective products	<input checked="" type="checkbox"/> pickout	<input type="checkbox"/> replace	<input type="checkbox"/> rework	


DETAILS

I. Quantity

Item Num ber	Ordered Quantity	Total carton	Packed Quantity	Finished quantity	Not finished quantity	Sample from packed Qty.	Sample from Notpacked Qty.
Blue	650	650	430	650	0	79	111
Pink	450	450	300	450	0	40	100
Tota	1100	1100	730	1100	0	119	211

II. Product description / style / color

1. Product description






Product view




Product view



Product view



Product view



Product view



Product view



Product view




Product view



Product view



Product view



Product view

N/A



11 Packing view



12 Packing view



13 Product view



14 Product view



15 Product view



16 Product view



17 Product view




18 Product view



19 Product view



20 Product view



21 Product view

N/A

2. Dimensions



Product size check



Product size check





Product size check



Product size check









9 Product size check	10 Product size check
	
Product weight check	Product weight check

III. Workmanship

Inspection Standard: ANSI/ASQZ1.4 (MIL-STD-105E)		DEFE CT S		
		Critical	Major	Minor
Sampling plan: Single, Normal	AQL	0.0	2.5	4.0
Inspection Level: Fixed sampling	Defects Found:	0	1	9
SampleSize:	330	/	/	/

Defectives List					
Defectives Description		CRI	MAJ	MIN	
Blue Sample:190 pieces					
1.	Untrimmed thread end 1.5-3cm	0	0	3	
2.	Dirty mark	0	0	2	
3.	Poor sewing	0	0	1	
Pink Sample:140 pieces					
4.	Broken stitches	0	1	0	
5.	Poor sewing	0	0	1	
6.	Dirty mark	0	0	1	
7.	Untrimmed thread end 3cm	0	0	1	

Defectives PIC
Blue

	
<p>1 Untrimmed thread end 1.5-3cm-minor</p>	<p>2 Untrimmed thread end 1.5-3cm-minor</p>
	
<p>3 Untrimmed thread end 1.5-3cm-minor</p>	<p>4 Dirty mark-minor</p>
	
<p>5 Dirty mark-minor</p>	<p>6 Poor sewing-minor</p>
<p>Pink</p>	

	
1 Broken stitches-major	2 Poor sewing-minor
	
3 Dirty mark-minor	4 Untrimmed thread end 3cm-minor

IV. TESTING /CHECKING

Inspection Standard: ANSI/ASQZ1.4 (MIL-STD-105E)				DEFECTS			
Sampling plan: Single, Normal				AQL	0	0.65	1.5
InspectionLevel:	S-2	SampleSize:	5	Max. Allowed:	0	0	0

TESTING/CHECKING							
NO	testitem	Insp Level	Sample	CRI	MAJ	MIN	Conclusion
1.	Cartondroptest	---	1 carton	0	0	0	PAS
2.	Odorcheck	S-2	5 sample	0	0	0	S
3.	Seamstrengthtest	S-2	5 sample	0	0	0	PAS
4.	Colorshadecheck	S-2	5 sample	0	0	0	S
5.	3MTapetest	S-2	5 sample	0	0	0	PAS
6.	Filler materialcheck	S-2	5 sample	0	0	0	S

7.	Rub test	S-2	5 sample	0	0	0	PASS
----	----------	-----	----------	---	---	---	------

Pictures & instructions

Carton drop test



N/A

Seam strength test





Rub test



Filler material check



3M Tape test



Color shade check



V . Data measurement

List of test data

Item	Contract requirements	Measured data
Carton size: cm	N/A	44x24.5x45
G.W.: kg	N/A	2.2
Product size: cm	N/A	231*145*20, 232*145*20, 231*145*20, 232*145*20, 235*145*20
Product weight: g	N/A	1.418, 1.48, 1.40, 1.402, 1.413,



Carton size check



Carton size check



Carton size check



Carton weight check

VI. PACKING

PACKING

Item: Blue



1 Carton view



2 Shipping mark



3 Shipping mark



4 Shipping mark



5 Shipping mark




6 Shipping mark



7 Shipping mark



8 Packing view



9 Packing view



10 Packing view




11 Packing view



12 Packing view



13 Packing view



14 Packing view



15 Packing view



16 Packing view



17 Packing view



18 Packing view

Item: Pink



1 Carton view



2 Shipping mark



3 Shipping mark



4 Shipping mark



5 Shipping mark



6 Shipping mark



7 Packing view



8 Packing view



9 Packing view



10 Packing view

VII. MARKING

SHIPPING MARK



<p style="text-align: center;">Blue</p>	<p style="text-align: center;">Blue</p>
<p style="text-align: center;">Blue</p>	<p style="text-align: center;">Pink</p>
<p style="text-align: center;">Pink</p>	<p style="text-align: center;">Pink</p>





Inspection spot



-----END OF REPORT-----